

**LiquiFilm™ is a water soluble plastic / film used as a purge gas barrier during TIG weld**

- Rapidly dissolves in water
- Possesses good barrier characteristics against Argon and Helium
- High resistance to pressure, allowing for greater positive pressure to be maintained in dammed area
- Highly flexible, allowing for easy use in any situation
- Can be punctured for gas inlets and outlets with out the risk of tearing or splitting



**How LiquiFilm™ Works**



1 Clean pipe with EZ Wipes



2 Apply LiquiFilm™ Water Soluble Adhesive to inside of pipe



3 Cut LiquiFilm™ in a circle 1.3 times greater than pipe diameter






4 Press glossy surface of LiquiFilm™ to tacky adhesive inside pipe

**LiquiFilm™ is available in Kit and Brick formats - Kit Includes**

- LiquiFilm™ Water Soluble Purge Dam Film (wound on core for easy dispense)
- Two 250 ml (8.5 fl oz.) bottles of LiquiFilm™ Water Soluble Adhesive
- Safety Cutting Knife
- Instruction Sheet



**Specifications for LiquiFilm™ Water Soluble LiquiFilm™ and Adhesive**

PART NO.	DESCRIPTION	WIPER SIZE	QTY / CARTON	ILLUSTRATION
WSF-1/20RG	LiquiFilm™ Water Soluble Purge Dam Kit	1 m x 20m (39" x 65ft)	12	
WSF-1/20B	LiquiFilm™ Water Soluble Purge Dam Kit (Block Format)	1 m x 20m (9" x 65ft)	12	
WSG-250	LiquiFilm™ Adhesive	250ml / bottle	48	
WSG-500	LiquiFilm™ Adhesive	500ml / bottle	24	